


Chapter 7 Phase Transformations

§ 7-1 Phase Transformations in Metals



A. The Kinetics of Phase Transformations

Kinetics - study of reaction rates of phase transformations

- measure degree of transformation as function of time (while holding temperature constant)


Solidification stages:

① Nucleation

- nuclei (seeds) act as templates on which crystals grow
- once nucleated, growth proceeds until equilibrium is attained

Nucleation Types

- **Homogeneous nucleation (均質成核)**
 - nuclei form in the bulk of liquid metal
 - requires considerable supercooling (typically 80-300°C)



$$r^* = \frac{-2\gamma T_m}{\Delta H_f \Delta T}$$

r^* = critical radius

γ = surface free energy

T_m = melting temperature

ΔH_f = latent heat of solidification

$\Delta T = T_m - T$ = supercooling


Driving force to nucleate increases as we increase ΔT

Small supercooling \Rightarrow slow nucleation rate - few nuclei - large crystals

Large supercooling \Rightarrow rapid nucleation rate - many nuclei - small crystals

• **Heterogeneous nucleation (異質成核)**

- much easier since stable “nucleating surface” is already present — e.g., mold wall, impurities in liquid phase
- only very slight supercooling (0.1-10°C)




$$\gamma_{IL} = \gamma_{SI} + \gamma_{SL} \cos \theta$$

$$r^* = - \frac{2\gamma_{SL}}{\Delta G_v}$$


$$\Delta G^* = \left(\frac{16\pi \gamma_{SL}^3}{3\Delta G_v^2} \right) S(\theta)$$

$$\Delta G_{het}^* = \Delta G_{home}^* S(\theta)$$



② Growth



Avrami equation $\Rightarrow y = 1 - \exp(-kt^n)$









§ 7-2 Microstructural and Property Changes in Iron-Carbon Alloys

A. Isothermal Transformation Diagrams (TTT, 恆溫相變化圖)

①. Eutectoid transformation: Transformation of austenite to pearlite








Coarse pearlite (粗波來鐵) \Rightarrow formed at higher temperatures - relatively soft

Fine pearlite (細波來鐵) \Rightarrow formed at lower temperatures - relatively hard

- **Bainite:** Non-Equilibrium Transformation Products
 - α lathes (strips) with long rods of Fe_3C
 - diffusion controlled.



Isothermal Transformation Diagrams (TTT, 恆溫相變化圖)





• 共析鋼恆溫相變化圖特徵


- ① 波來鐵不易在溫度接近 A_1 時出現
- ② 增加過冷度 (低於 A_1)，縮短波來鐵變態時間
- ③ 變態鼻部出現在 540°C ，且變態時間僅需數秒鐘
- ④ 變態溫度低於 540°C ，
非層狀的肥粒鐵 + 雪明碳鐵 (變韌鐵) 出現
- ⑤ 變態溫度急速降低至 200°C ，形成麻田散鐵

• Martensite:

- γ (FCC) to Martensite (BCT)
- γ to M transformation..
- is rapid!
- % transf. depends on T only.




— Martensite needles
— Austenite




②. Mechanical Behavior of Iron-Carbon Alloys


- Increase C content: TS and YS increase, $\%EL$ decreases
- Hardness: martensite \gg fine $>$ coarse $>$ spheroidite
- $\%RA$: martensite \ll fine $<$ coarse $<$ spheroidite



B. Continuous Cooling Transformation Diagrams (CCT, 連續冷卻相變化圖)




①. Superimposition of isothermal & continuous cooling transformation diagrams



共析鋼的 CCT 圖特徵

- ① CCT 圖中，波來鐵的變態起始與變態終止時間延遲
- ② CCT 圖中沒有變韌鐵出現
- ③ CCT 圖中出現變態中止線


②. Critical cooling rate



Upper critical cooling rate (上臨界冷卻速率)

Lower critical cooling rate (下臨界冷卻速率)

③. CCT curve for the 4340 steel alloy



鋼材中添加合金元素的目的

- ① 提高硬化能 (hardenability)
- ② 改善鋼材機械性質
- ③ 提供肥粒鐵的固溶強化
- ④ 產生合金碳化物，增加鋼材耐蝕、耐熱、耐磨等特性

§ 7-3 Heat Treatment of Steels


A. Annealing (退火): Heat to T_{anneal} , then cool slowly

退火的目的

- ① 消除由冷卻或由常溫加工時所產生的應力
- ② 降低硬度
- ③ 改良材料的機械加工性
- ④ 調整結晶組織
- ⑤ 獲得所需的機械性質或物理性質
- ⑥ 消除化學成分的不均勻性

退火的種類

- ① 完全退火 (full annealing)
- ② 弛力退火 (stress relief annealing)
- ③ 製程退火 (process annealing).....



B. Normalizing (正常化)

正常化的目的

調整不良鑄造或鍛造組織，使其獲得略近於平衡狀態組織，以利後續工作

C. Homogenizing (均質化)


均質化的目的


利用擴散作用消除鋼材內部巨觀或微觀的化學成分偏析現象

D. Spheroidizing (球化處理)

球化處理的目的

改善過共析鋼的切削性和塑性加工性、或增加材料淬火後的韌性





E. Quenching & Tempering (淬火與回火)

淬火的目的是

使鋼材獲得麻田散鐵組織

回火的目的


消除淬火鋼材的內部應力，調節硬度，改善韌性

⌘ 回火過程鋼鐵材料的組織變化：(麻田散鐵 → 回火麻田散鐵)

- ① 第一階段：麻田散鐵 → 低碳麻田散鐵 + ϵ 碳化物
- ② 第二階段：殘留沃斯田鐵 → 變韌鐵
- ③ 第三階段：低碳麻田散鐵 + ϵ 碳化物 → 肥粒鐵 + 雪明碳鐵
- ④ 第四階段：雪明碳鐵 → 合金碳化物 (針對合金鋼)

Tempering Martensite

- reduces brittleness of martensite,
- reduces internal stress caused by quenching.




- produces extremely small Fe_3C particles surrounded by α .
- decreases TS, YS but increases %RA

F. Hardenability (硬化能)



- 定義：鋼材在相同淬火條件下，材料斷面硬化之深度及硬度之分佈性能
 ⇒ Ability to form martensite

- 硬化能試驗：

① The Jominy End-Quench Test




Hardness versus distance from the quenched end




- **Hardenability:** 4340 > 4140 > 8640 > 5140 > 1040

② CCT curves




③ Ideal Critical Diameter (DI, 理想臨界直徑)



• 影響鋼材硬化能的因素：

- ① 含碳量
- ② 淬火液種類
- ③ 尺寸效應
- ④ 沃斯田鐵晶粒尺寸
- ⑤ 合金元素種類及含量

• Effect of carbon content:




• Effect of quenching medium:

Medium	Severity of Quench	Hardness
air	low	low
oil	moderate	moderate
water	high	high

• Effect of geometry:

When surface-to-volume ratio increases:

- cooling rate increases
- hardness increases







§ 7-4 Precipitation Hardening (Age hardening)

⇒ 藉由析出物阻止差排移動以增強材料強度


Procedure:

solution heat treatment ⇒ quench to room temperature ⇒ precipitation


固溶處理 ⇒ 淬火 ⇒ 析出硬化



Strength and hardness as a function of the aging time at constant temperature



The strengthening process is accelerated as the temperature is increased.



§ 7-5 Glass Transition Phenomena in Polymers



The temperature at which the polymer experiences the transition from rubbery to rigid states is called the **glass transition temperature, T_g** .

What factors affect T_m and T_g ?

Both T_m and T_g increase with increasing chain stiffness

- Chain stiffness increased by presence of
 1. Bulky side groups
 2. Polar groups
 3. Chain double bonds and aromatic chain groups

- Regularity of repeat unit arrangements – affects T_m only
- Increasing the molecular weight tends to raise T_m and T_g .



§ 7-5 Summary

- Heat treatments of Fe-C alloys produce microstructures including: -- pearlite, bainite, spheroidite, martensite, tempered martensite
- Precipitation hardening
 - hardening, strengthening due to formation of precipitate particles.
 - Al, Mg alloys precipitation hardenable.
- Melting and glass transition temperatures for polymer
 - Both T_m and T_g increase with increasing chain stiffness
 - Regularity of repeat unit arrangements – affects T_m only
 - Increasing the molecular weight tends to raise T_m and T_g .